ATTACHIENT B

- 1 -

"KOVOHUTE", nar. podnik, zavod Velvary. "KOVOHUTE", Nat. Entorpr., Velvary Plant

HOVORU IB SHEET ESTAGE	pro . valvaty frant
hegenda k prilozo c.l	Legend to the Enclosure No. 1.
1.) Rutni hale c.1	Hell No. 1
2.) Rutni hela c. 2, t. ev. "Nove hale"	Hall No. 2, so-called "New Hall"
3.) Eutni hala c. 3, t. zv. "Zinkovna"c.	Hall No. 3, so-called "Zinkovna" No.3
4a) Kotelna	Boiler house
5.) Rozvodna elektricka stanice	Switch-board room
5.) Vyzkumne kovu "Elektron"	"Electron" metal research laboratory
7.) Technicka laborator	Technical laboratory
8.) Hutni hala c.4 (ve wystawbe)	Hall No. 4 (under construction)
9.) Paketyrka	Packaging room
10.) Zemecnicka dilna	Fitter's shop
11.) Skladiste pro zam. dilnu	Stores for fitter's shop
12.) Truhlerske dilna	Joiner's shop
15.) Kencelar dilenskeho mistra	Office of Foreman of No. 10 (above)
14.) Uctarna a kancelar red. podniku	Accounting offide and office of the director
15.) Administrativni kancelar	Administration office
16.) Skladiste cinu a surovin po-	Tin and raw materials stores
trobnych k vyrobe 17.) Chemicka laborator	Chemical laboratory
18.) Transformator	Transformer
19.) Nadrz a corpadlo nafty a oleje	Cistern and pump for naphtha and oil
20.) Kulna so dvema nuskema do 50mm	Shed with 2 shears, cap. :50 mm
21.) Komin pece c. 3, t. 2v. "Plamenky"	Chimney of Furnace No. 3, so called "Plamenka".
22.) Komin pece c.l,t,zv. Kotel "	Chimney of Furnace No. 1, so called "Kotel" ("Boiler")
25.) Komin ke kotekue	Boiler house chirmey
24.) Skladisto oleje a benzinu	Gasoline and oil stores
25.) Zachody	7.0.
26.) Allny c plose 220m ² ,6 kusu a.) kulna pro paketovani med dratu b.) Sklad mosaznych trisek c) Sklad RG d.) Sklad cervene slitiny e.) Sklad sinkove slitiny f.) Sklad cisteho zinku	Six sheds, each 220 sc.m. in area Shed for packaging of copper wire Store of brass scrap RG (sic) stores Stores of copper alloy Stores of tin alloy stores of pure tin (Polish)

Approved For Release

SECRE

ATTACHMENT B

- 3 -

Pokracovani	legendy	k	pril.c.l.	
		-	P. C. C. C. C.	

Cont. of the Legend to the Ecl. No. 1.

51.) Drubeznik

Poulterer

52.) Chlev pro vepre

Pigoty

55.) Skied pro howy wedeny a

Stores of finished copper and brass

mosseny waterial

goods ·

54.) Vysoka pec – neni v provosu

Blast furnace (not in operation)

55.) Plynojem, ktery v pripade ugavremi plynoveho privodu v nutnych pripadoch, vydrzi zasobit a udrzet pece v provogu 24 hod.

Spare gas tank, which in case of disruption of regular gas supply can supply and maintain the furnaces for 24 hours.

56.) Vjezd do tovarny

Factory entrance

57.) Vyjezd z tovarny

Factory exit

58,) Sklad entimonu

Stores of antimony

59.) Hut pro strikenou pajku

Smelting house for solder

- 2 -

ATTACHLENT B

Pokracovani 1	egendy k prilo 1,	Cont. of the Legend to the	anc.

- 27.) Komin pro balu c. 2
- d) Odsavaci centrala a zachytna stanics pro zinkovy proud od poei pro zinkove slitiny.
- 29.) Plynova centrala
- 30.) Boxy pro semot na wyzdiwani
- 51.) Samotarna pro vyzdavana rota cich peci
- 52) Garage
- 25 / Vodama
- 34.) Prostor kde je ukladena zelonina a pod pro zav. jidelnu
- 55.) Bason na koupsui
- 56.) Pradelna
- 37.) Park
- 58.) Obytas vila tovarniho redit.
- 39.) Ovocna zahrada
- 40,) Boxy pro ruzne kovove piliny a trisky
- 41.) Zavodni jidelna s.) kuchyne,b.)kanc. zev. rady
- 42.) Vratnice c. 2
- 43.) Boxy pro trisky
- 44.) Tovarni vlecka
- 45.) Boxy pro clownate popele a prechy
- 46.) Vratnice c. 1
- 47.) Yaha do 5 tum
- 48.) Pumpa pro solanku na chlazeni ruznych strikmych pajek
- 49.) Cesta pro sklad odpadoveho meterialu(srot)
- 50.) Sklad odpadoveho materialu a, Bilad oloveneho srotu
 - b. Hilad mosezneho erotu
 - c. Dictad mediciono arosu
 - d. Bklad medenych civek

cl.No.l.

Chimney of Hall No. 2

Exhausting plant and collecting receiver for melted zinc from the furnaces for zinc alloys.

Gas station

Fire bricks for furnaces

Fire brick workshop for rotary furnaces.

Garages

Water tower

Place where vegetables and other articles for the canteer are stored.

Swimming pool

Laundry

Park

House of the Factory Manager

Orchard

Boxes for various metal filings and scrap.

Plant canteen a.) Kitchen, b.) Office of the Factory

Boxes for metal scrap

Council Guardroom No. 2

Factory railroad track

Boxes for plumbiferous ashes and dusts.

Guardroom No. 1

Weighing machine, up to 5 tons

Pump for salt solution (coolant) for refrigeration of various solders

Road to scrap stores

Scrapping stores

- a.) Stores of lead scrap
- b.) Stores of brass scrapc.) Stores of copper scrap
- d.) Stores of copper (reels)

SECRET/CONTROL - U.S. OFFICIALS ONLY